



## Fouling Effect on Heatexchanger











**COSTLY FIN DAMAGE** 














GEA-Ovelrahr klein/grad Disensestellung 3\*



Alex-Sündel (SEA) Flair-Bündel (Balcke, Hanon) Süsenanstellung (\*




Buicke-Ripperrohrbündel Disenunstellung 17,5°










## References

## Air-cooler Performance










Penetration see during AFC cleaning in progress





## AFC external cleaning





CONTAMINATION WASHED OUT DURING AIR-FIN-COOLER CLEANING





